



To

The Principal,
G.M.S.S.S. School,
Rampur Sarsehri (Ambala).

No. 2127 Dated: 9/6/2023

Subject: Structure safety Certificate.
(G.M.S.S.S. School, Rampur Sarsehri (Ambala))

Reference: Your office Letter No. 23 / 428 dated 20.04.2023.

In this connection, it is intimated that the SDE, PSD-6 has reported that the school building i.e. Govt. Model Sanskriti Sr. Sec. School, Rampur Sarsehri (Ambala) has been inspected by the SDE alongwith JE concerned and visually it found safe for running school. Hence, the school Building Safety Certificate is hereby given upto the period 2023 – 23 with the following conditions: -

1. Building of this School should be repaired every year.
2. Water should not be allowed to stagnate around and on the roof of the Building.
3. If Building is found cracked from anywhere, the same should be got vacated immediately and same should be got repaired immediately.
4. Institution will be responsible for safety of building from every angle and Fire-Fighting equipment should be in functional condition.
5. If the building of the school is to be extended, the same should be first approved from Structural Engineer and may be intimated to Department.

This is for your kind information.

DA/NIL

Executive Engineer,
Provincial Division No.1,
PWD B&R Br; Ambala Cantt.

Endst. No.

Dated:-

Copy of the above is forwarded to the Sub Divisional Engineer, Provincial Sub Division No. 6, PWD B&R Br; Ambala Cantt for information w.r.t. this office No. 165 dated 01.05.2023.

DA/ NIL

Executive Engineer,
Provincial Division No.1,
PWD B&R Br; Ambala Cantt.